







MONTERINGSANVISNINGAR
INSTALLATION
MONTAGEANLEITUNG
INSTRUCTIONS MONTAGE
INSTRUCCIONES DE MONTAJE
ISTRUZIONI DI MONTAGGIO

FUMEX

PR 5000





- ⊛ Torx 30
- ⊛⊛ Torx 10
- ⊛⊛⊛ 13 mm

